BROOKHAVEN NATIONAL LABORATORY

Work Permit # DRL-2010-2
Work Order # _____
Job# _____ Activity# _____

1. Work requester fills out this section. ☐ **Standing Work Permit**

Requester: Don Lynch	Date: 01/25/2010	Ext.: 2253	Dept/Div/Group: PO/PHENIX
Other Contact person (if different from requester): Carter Biggs			Ext.: 7515
Work Control Coordinator: Don Lynch		Start Date: 1/27/2010	Est. End Date: 1/31/2010
Brief Description of Work: Repair/ r detectpr chamber wires on Drift Chamber on PHENIX West Carriage			
Building: 1008	Room: IR	Equipment: DC East detctor	Service Provider: PHENIX collaborators

. WCC, Requester/Designee, Service Provider, and ES&H (as necessary) fill out this section or attach analysis

ES&H ANALYSIS				
Radiation Concerns	☒ None	☐ Activation	☐ Airborne	☐ Contamination	☐ Radiation
Radiation Generating Devices:	☐ Radiography	☐ Moisture Density Gauges	☐ Soil Density Gauges	☐ X-ray Equipment
☐ Special nuclear materials involved, notify Isotope Special Materials Group			☐ Fissionable materials involved, notify Laboratory Criticality Officer	
Safety Concerns	☐ None	☐ Ergonomics	☐ Transport of Haz/Rad Material	
☐ Adding/Removing Walls or Roofs	☐ Confined Space*	☐ Explosives	☐ Lead*	☐ Penetrating Fire Walls
	☐ Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*	☐ Material Handling	☐ Rigging/Critical Lift
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*
☐ Biohazard*	☒ Elevated Work*	☐ Hydraulic	☐ Non-ionizing Radiation*	☐ Vacuum
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	☒ Other Purge Flammable Gas Prior to repair procedure
* Does this work require medical clearance or surveillance from the Occupational Medicine Clinic? ☐ Yes ☒ No				
Environmental Concerns		☒ None	☐ Work impacts Environmental Permit No.	
☐ Atmospheric Discharges (rad/non-rad)		☐ Land Use	☐ Soil Activation/contamination	☐ Waste-Mixed
☐ Chemical or Rad Material Storage or Use		☐ Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive
☐ Cesspools (UIC)		☐ Oil/PCB Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping
Waste disposition by:				☐ Other
Pollution Prevention (P2)/Waste Minimization Opportunity:		☒ None ☐ Yes		
FACILITY CONCERNS	☒ None			
☐ Access/Egress Limitations	☐ Electrical Noise	☐ Potential to Cause a False Alarm		☐ Vibrations
	☐ Impacts Facility Use Agreement		☐ Temperature Change	☐ Other
☐ Configuration Control	☐ Maintenance Work on Ventilation Systems		☐ Utility Interruptions	
WORK CONTROLS				
Work Practices				
☐ None	☐ Exhaust Ventilation	☒ Lockout/Tagout	☐ Spill Containment	☐ Security (see Instruction Sheet)
☒ Back-up Person/Watch	☐ HP Coverage	☐ Posting/Warning Signs	☐ Time Limitation	☐ Other
☐ Barricades	☐ IH Survey	☐ Scaffolding-requires inspection	☐ Warning Alarm (i.e. “high level”)	
Protective Equipment				
☐ None	☐ Ear Plugs	☐ Gloves	☐ Lab Coat	☐ Safety Glasses
☐ Coveralls	☐ Ear Muffs	☐ Goggles	☐ Respirator	☐ Safety Harness
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	☒ Safety Shoes ☐ Other
Permits Required (Permits must be valid when job is scheduled.)				
☒ None	☐ Cutting/Welding	☐ Impair Fire Protection Systems		
☐ Concrete/Masonry Penetration	☐ Digging/Core Drilling	☐ Rad Work Permit-RWP No		
☐ Confined Space Entry	☐ Electrical Working Hot	☐ Other		
Dosimetry/Monitoring				
☒ None	☐ Heat Stress Monitor	☐ Real Time Monitor	☐ TLD	
☐ Air Effluent	☐ Noise Survey/Dosimeter	☐ Self-reading Pencil Dosimeter	☐ Waste Characterization	
☐ Ground Water	☐ O_2/Combustible Gas	☐ Self-reading Digital Dosimeter	☐ Other	
☐ Liquid Effluent	☐ Passive Vapor Monitor	☐ Sorbent Tube/Filter Pump		
Training Requirements (List below specific training requirements)				
PHENIX Awareness, LockOut/TagOut affected, RHIC Access, working at heights, PHENIX Awareness				
Based on analysis above, the Walkdown Team determines the risk, complexity, and coordination ratings below:			**If using the permit when all hazard ratings are low, only the following need to sign: (Although allowed, there is no need to use back of form)**	
ES&H Risk Level:	☒ Low ☐ Moderate ☐ High		WCC:	Date:
Complexity Level:	☒ Low ☐ Moderate ☐ High		Service Provider:	Date:
Work Coordination:	☐ Low ☒ Moderate ☐ High		Authorization to start	Date:
			(Departmental Sup/WCC/Designee)	

3. Both work requester and service provider contribute to work plan (use attachments for detailed plans)

Work Plan (procedures, timing, equipment, and personnel availability need to be addressed): See Attached
Special Working Conditions Required: No
Operational Limits Imposed: No
Post Work Testing Required: No
Job Safety Analysis Required: ☐ Yes ☒ No Walkdown Required: ☒ Yes ☐ No

Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature means that the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.

Title	Name (print)	Signature	Life #	Date
Primary Reviewer				
ES&H Professional				
Other				
Other				
Work Control Coordinator	Don Lynch		20146	
Service Provider				
	Review Done: ☐ in series	☐ team		

4. Job site personnel fill out this section.

Note: Signature indicates personnel performing work have read and understand the hazards and permit requirements (including any attachments).			
Job Supervisor:		Contractor Supervisor:	
Workers:	Life#:	Workers :	Life#:
Workers are encouraged to provide feedback on ES&H concerns or on ideas for improved job work flow. Use feedback form or space below.			

5. Departmental Job Supervisor, Work Control Coordinator/Designee

Conditions are appropriate to start work: (Permit has been reviewed, work controls are in place and site is ready for job.)			
Name:	Signature:	Life#:	Date:

6. Departmental Job Supervisor, Work Requester/Designee determines if Post Job Review is required. ☐ Yes ☐ No

Post Job Review (Fill in names of reviewers)			
Name:	Signature:	Life#:	Date:
Name:	Signature:	Life#:	Date:

7. Worker provides feedback.

Worker Feedback (use attached sheets as necessary)
a) WCM/WCC: Is any feedback required? ☐ Yes ☐ No

b) Workers: Are there better methods or safer ways to perform this job in the future? ☐ Yes ☐ No

8. Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition. (WCC can delegate clean up of work area to work supervisor)

Name:	Signature:	Life#:	Date:
Comments:			

Attachment to W.P. # DRL-2010-2 January 25, 2010

Drift Chamber repair in the PHENIX Experimental Hall (bldg. 1008).

Problem

A broken detector wire has been discovered which requires repair by removal of the broken wire. The repair effort will require access from the extended CM lift table.

Access to the elevated locations is difficult, as they are located 10 to 20 feet above track level, tucked inside the arc formed by the RICH detector, with the Central Magnet in front of the west carriage. The procedures described below were used successfully in the past to trouble shoot and repair failed chamber wires.

Work Plan

This work is to be done by fully trained and experienced personnel during a periodic maintenance access day during Run 10

DC Chamber wire troubleshooting and repair

Access will be from the CM lift table with extension wings and elevation step attachment.

Prior to commencing the repair effort:

1. Flammable gas shall be purged from the DC West detector subsystem using gaseous Nitrogen continuously until the flammable gas content is reduced to less than 10%.

2. The PHENIX magnets are to be turned off and locked out.

3. The PHENIX flammable detection system shall be put into bypass mode (until repairs have been completed.

4. Safety rail on elevation step must be attached as shown in the photo below.

Experienced DC group technicians will troubleshoot the shorted Chamber wire(s) by carefully slicing into the DC chamber at a known short location, located and remove the failed wire eliminating the short, then resealing the chamber, testing and verifying the repair.

The west carriage shall be in its run position for this repair. Access to the CM region shall be from the east side.

After completion of the repairs, restore the flammable gas detection system to normal operating mode, remove all tools and equipment from the CM region and remove the CM extension step and return it to storage for future use.



CM Lift Table Extension Step and safety rail